

### **SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Run date 22-Nov-14 Time 3:45 PM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

### Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Const Calendar Day: Diary #: 054 199 Date: 26-Mar-2010 Friday Inspector Name: He, Philip Title: Transportation Engineer

Inspection Type:

Shift Hours: 06:30 am 05:00 pm **Break:** Over Time: 02:00

Federal ID: Location:

Reviewer: Approved Date: Liu, Tai-Lin 20-Apr-10 Status: Approved

Weather

Temperature 7 AM 4PM 12 PM Precipitation Condition

Working Day If no, explain:

04-0120F4 X-L03-CBM.056 E-W Line Cross Over Lift 03 Cross Beam Bid Item: 056 AMERICAN BRIDGE/FLUOR, A JV

Dispute Diary:

056 X-L03-CBM.056 Work description.

1. Fixed the remaining problems in the jacks in the gantry system.

- 2. Pushing the crossbeam 02 in the gantry from "W" line temp. truss to join the OBG Lift L3E.
- 3. Continueous splicing the crossbeam to L2E. Darryl's group is doing the bolt splicing for the operation.
- 4. Installing welding side platform for the splicing at "W" line between L1W and L2W.
- 5. Preparing Crossbeam03 at Pier 7.
- 6. Adjusting both "E" line and "W" line OBG Lifts using vertical jacks from 8:40am. Jacking pressure for each support has been recorded:

"E" Line OBG Lifts:

Jacking pressure of OBG Lift L1E

ure)

Jacking pressure of OBG Lift L2E

==============================



Page 1 of 5

Job Name: 04-0120F4 Inspector Name He, Philip Diary #: 054 Date: 26-Mar-2010 Friday

Support Location	Jack Number	Jacking Pressure (Stable Pressure)
==========	========	=======================================
NW:	08	3300 psi
NE:	01	3100 psi
SW:	12	3000 psi
SE:	11	3300 psi

#### Jacking pressure of OBG Lift L3E

Support Location	Jack Number	Jacking Pressure (Stable Pressure)
==========	=========	=======================================
NW:	16	3500 psi
NE:	04	2600 psi
SW:	15	1050 psi
SE:	18	2550 psi

#### Jacking pressure of OBG Lift L4E

Jack Number	Jacking Pressure (Stable Pressure)
========	=======================================
13	2600 psi
28	3200 psi
19	2200 psi
24	330 psi
	13 28 19

"W" Line OBG Lifts:

Jacking pressure of OBG Lift LWE

============================

Support Location	Jack Number	Jacking Pressure (Stable Pressure)
==========	========	=======================================
NW:	46	4500 psi
NE:	26	3800 psi
SW:	47	4100 psi
SE:	21	2600 psi

### Jacking pressure of OBG Lift L2W

Support Location	Jack Number	Jacking Pressure (Stable Pressure)
==========	========	=======================================
NW:	25	2000 psi
NE:	31	3650 psi
SW:	22	2150 psi
SE:	33	1600 psi



Job Name: 04-0120F4 Inspector Name He, Philip Diary #: 054 Date: 26-Mar-2010 Friday

#### **Attachment**





Crossbeam 03 Being Prepared at Pier 7



Gantry Sitting on Temp. Truss



Installation of the Welding Side Platform



Gantry Sitting on Temp. Truss



Pushing Crossbeam 02 to Join OBG Lift L3E

Job Name: 04-0120F4 Inspector Name He, Philip Diary #: 054 Date: 26-Mar-2010 Friday




Gantry Sitting on Temp. Truss



Pushing Crossbeam 02 to Join OBG Lift L3E



Installation of the Welding Side Platform



Pushing Crossbeam 02 to Join OBG Lift L3E



Pushing Crossbeam 02 to Join OBG Lift L3E



Pushing Crossbeam 02 to Join OBG Lift L3E

Job Name: 04-0120F4 Inspector Name He, Philip Diary #: 054 Date: 26-Mar-2010 Friday



Pushing Crossbeam 02 to Join OBG Lift L3E



Pushing Crossbeam 02 to Join OBG Lift L3E



Installation of the Welding Side Platform



Pushing Crossbeam 02 to Join OBG Lift L3E



Pushing Crossbeam 02 to Join OBG Lift L3E